INSPECTION FORM
OFFICE OF CONSERVATION
INJECTION & MINING DIVISION
617 NORTH 3RD STREET
BATON ROUGE, LA 70802

Location: Sulphur Mines Dome

Date: Monday, August 25, 2025 Time of Arrival: 9:00 AM Time of Departure: 1:00 PM

Inspector Name(s): Billy Carnes

Other personnel on site: Josh Bradley [Westlake] Vance Hill [Yellowrock]

Weather Conditions (Temp/Wind Speed/Direction, etc.): 83* to 91* 6 mph ENE clear-sunny

Any planned work for today:

Inspection locations: Sulphur Mines Salt Dome	**Cavern 6X**	**Cavern Well 7A**	**Cavern Well 7B**	**CL-1** (near BW-22, west side of Central Lake)	**Cavern Well 2**	**Cavern Well 2a**	**Cavern Well 4**	**Cavern Well 20**		**Yellowrock**
R & R construction working on containment levee. Lonquist is working on Cavern 2 & 4 with Wireline on both caverns. Josh Bradley stated that they may have found a hole in Casing around 870' in Cavern Well 2.		Fluid on pad bubbling observed	injecting 530 gpm // bottom hole gauge reading 1469 psi	Still bubbling w/ oil sheen	Well is out of service // Wireline on Well		Well is out of service // Wireline is on Well			#1017 20 psi tubing 20 psi casing// #1012 40 psi tubing 40 psi casing// S-7 70 psi tubing 0 psi casing// S-4 18 psi tubing 210 psi casing
Tubing Pressure (if applicable)			100 psi							
Casing Pressure (if applicable)	613 psi		420 psi			1.02 psi		507 psi		
Bubbling?		yes		yes						
Sheen?		no		yes						
Oil?		no		yes						
Odor?		no		yes						
Any new remedial work?		no		no						
Any impact to vegetation?		no		no						
Any impact to wildlife?		no		no						