INSPECTION FORM
OFFICE OF CONSERVATION
INJECTION & MINING DIVISION
617 NORTH 3RD STREET
BATON ROUGE, LA 70802

Location: Sulphur Mines Dome

Date: Tuesday, September 2, 2025 Time of Arrival: 9:00 AM Time of Departure: 1:00 PM

Inspector Name(s): Billy Carnes

Other personnel on site: Vance Hill [Yellowrock] Josh Bradley [Westlake]

Weather Conditions (Temp/Wind Speed/Direction, etc.): 79* to 89* clear - sunny 5 mph NE

Any planned work for today: Cheak bubbling site's, Cavern Well pressures & some of Yellowrock Well pressure's

Inspection locations: Sulphur Mines Salt Dome	**Cavern 6X**	**Cavern Well 7A**	**Cavern Well 7B**	**CL-1** (near BW-22, west side of Central Lake)	**Cavern Well 2**	**Cavern Well 2a**	**Cavern Well 4**	**Cavern Well 20**		**Yellowrock**
R & R working on containment levee. MC company is preparing for sheet pile containment wall		Fluid on pad bubbling observed	injecting 523 gpm // 1470 psi on down hole gauge	Still bubbling with Oil sheen	Cavern Well 2 has a Plug in Casing blocking casing hole from cavern. This cavern is being monitor by Cavern 4 pressure gauges					#1017 20 psi tubing 20 psi casing// #1012 40 psi tubing 40 psi casing// S-7 70 psi tubing 0 psi casing// S-4 18 psi tubing 210 psi casing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)			100 psi							
Casing Pressure (if applicable)	612 psi		419 psi			0.85 psi	224 psi	507 psi		
Bubbling?		yes		yes						
Sheen?		no		yes						
Oil?		no		yes						
Odor?		no		yes						
Any new remedial work?		no		no						
Any impact to vegetation?		no		no						
Any impact to wildlife?		no		no						