INSPECTION FORM
OFFICE OF CONSERVATION
INJECTION & MINING DIVISION
617 NORTH 3RD STREET
BATON ROUGE, LA 70802

Location: Sulphur Mines Dome

Date: Monday, September 8, 2025 Time of Arrival: 10:30 AM Time of Departure: 1:00 PM

Inspector Name(s): Billy Carnes

Other personnel on si DeAnn Ch

Weather Conditions (Temp/Wind Speed/Direction, etc.): 77* to 85* Sunny/Clear NE 8 mph

Any planned work for today: Check bubbling site's, Cavern Well pressures & some pressures on Yellowrok wells

Inspection locations: Sulphur Mines Salt Dome	**Cavern 6X**	**Cavern Well 7A**	**Cavern Well 7B**	**CL-1** (near BW-22, west side of Central Lake)	**Cavern Well 2**	**Cavern Well 2a**	**Cavern Well 4**	**Cavern Well 20**		**Yellowrock**
M & C Oilfield services working on sheet pile containment levee		Pad dry no bubbling observed	injecting 520 gpm // 1470 psi on downhole gauge	Still bubbling with oil sheen	This well has a plug set in casing below a hole in casing.					#1017 130 psi tubing 130 psi casing// #1012 40 psi tubing 40 psi casing// S-7 70 psi tubing 0 psi casing// S-4 18 psi tubing 200 psi casing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)			98 psi							
Casing Pressure (if applicable)	611 psi		420 psi			0.66 psi	240 psi	470 psi		
Bubbling?				yes						
Sheen?				yes						
Oil?				yes						
Odor?				yes						
Any new remedial work?				no						
Any impact to vegetation?				no						
Any impact to wildlife?				no						