INSPECTION FORM
OFFICE OF CONSERVATION
INJECTION & MINING DIVISION
617 NORTH 3RD STREET
BATON ROUGE, LA 70802

Location: Sulphur Mines Dome

Date: Tuesday, September 23, 2025 Time of Arrival: 9:30 AM Time of Departure: 12:00 PM

Inspector Name(s): Billy Carnes

Other personnel on site: Josh Bradley [Westlake] Vance Hill [Yellowrock]

Weather Conditions (Temp/Wind Speed/Direction, etc.): 83* to 85* S 7 mph cloudy with some lite rain

Any planned work for today: Check some bubbling site's, Westlake cavern Well pressure's & some of Yellowrock Well pressure's

Inspection locations: Sulphur Mines Salt Dome	**Cavern 6X**	**Cavern Well 7A**	**Cavern Well 7B**	**CL-1** (near BW-22, west side of Central Lake)	**Cavern Well 2**	**Cavern Well 2a**	**Cavern Well 4**	**Cavern Well 20**		**Yellowrock**
R & R construction working on Levee and M & C oilfield services is working on the Sheet Piles levee		Pad dry no bubbling observed	Injecting 504 gpm, Downhole gauge 1470 psi	Still bubbling with oil sheen	Well has a temporary plug in the Well casing so the surface Pressure reading isn't correct on the Cavern Pressure.					#1017 90 psi tubing 90 psi casing// #1012 40 psi tubing 40 psi casing// S-7 70 psi tubing 0 psi casing// S-4 18 psi tubing 195 psi casing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)			98 psi							
Casing Pressure (if applicable)	610 psi		418 psi			0.39 psi	208 psi	431 psi		
Bubbling?				yes						
Sheen?				yes						
Oil?				yes						
Odor?				yes						
Any new remedial work?				no						
Any impact to vegetation?				no						
Any impact to wildlife?				no						