INSPECTION FORM
OFFICE OF CONSERVATION
INJECTION & MINING DIVISION
617 NORTH 3RD STREET
BATON ROUGE, LA 70802

Location: Sulphur Mines Dome

Date: Monday, October 6, 2025 Time of Arrival: 9:30 AM Time of Departure: 1:00 PM

Inspector Name(s): Billy Carnes

Other personnel on site: Josh Bradley [Westlake] Vance Hill [Yellowrock]

Weather Conditions (Temp/Wind Speed/Direction, etc.): 76* to 87* Sunny/clear NNE 3 mph

Any planned work for today: Check bubbling site's, Cavern Well pressures & check some Yellowrock well pressure's

Inspection locations: Sulphur Mines Salt Dome	**Cavern 6X**	**Cavern Well 7A**	**Cavern Well 7B**	**CL-1** (near BW-22, west side of Central Lake)	**Cavern Well 2**	**Cavern Well 2a**	**Cavern Well 4**	**Cavern Well 20**		**Yellowrock**
R & R Construction working on containment levee. M & C Oilfield services working on cleaning drainage ditches.		Pad dry no bubbling observed	Injecting 504 gpm 1474 down hole gauge	still bubbling w/oil sheen	Well has a plug in the casing .. Well is offline					
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)			108 psi							
Casing Pressure (if applicable)	609 psi		425 psi			0.74 psi	221 psi	484 psi		
Bubbling?				yes						
Sheen?				yes						
Oil?				yes						
Odor?				yes						
Any new remedial work?				no						
Any impact to vegetation?				no						
Any impact to wildlife?				no						