INSPECTION FORM
OFFICE OF CONSERVATION
INJECTION & MINING DIVISION
617 NORTH 3RD STREET
BATON ROUGE, LA 70802

Location: Sulphur Mines Dome

Date: Monday, October 20, 2025 Time of Arrival: 9:00 AM Time of Departure: 12:30 PM

Inspector Name(s): Billy Carnes

Other personnel on site: DeAnn Chapman [Westlake] Vance Hill [Yellowrock]

Weather Conditions (Temp/Wind Speed/Direction, etc.): 62* to 80* Sunny/clear 6 mph ESE

Any planned work for today: Check bubbling site's, Cavern Well pressures & Check some of Yellowrock's Well pressures

Inspection locations: Sulphur Mines Salt Dome	**Cavern 6X**	**Cavern Well 7A**	**Cavern Well 7B**	**CL-1** (near BW-22, west side of Central Lake)	**Cavern Well 2**	**Cavern Well 2a**	**Cavern Well 4**	**Cavern Well 20**		**Yellowrock**
R & R Construction working on containment levee		Pad dry no bubbling observed	Injecting 532 gpm// 1470 psi on Down hole gauge	Still bubbling w/ oil sheen	is out of service					#1017 150 psi tubing 150 psi casing// #1012 40 psi tubing 40 psi casing// S-7 70 psi tubing 0 psi casing// S-4 18 psi tubing 180 psi casing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)			101 psi							
Casing Pressure (if applicable)	609 psi		420 psi			0.15 psi	233 psi	484 psi		
Bubbling?				yes						
Sheen?				yes						
Oil?				yes						
Odor?				yes						
Any new remedial work?				no						
Any impact to vegetation?				no						
Any impact to wildlife?				no						