INSPECTION FORM
OFFICE OF CONSERVATION
INJECTION & MINING DIVISION
617 NORTH 3RD STREET
BATON ROUGE, LA 70802

Location: Sulphur Mines Dome

Date: Monday, October 27, 2025 Time of Arrival: 9:30 AM Time of Departure: 1:00 PM

Inspector Name(s): Billy Carnes

Other personnel on site: Kevin LaVergne [Westlake] Vance Hill [Yellowrock]

Weather Conditions (Temp/Wind Speed/Direction, etc.): 70* to 80* NNE 2 mph clear/Sunny

Any planned work for today: Check bubbling site's, Cavern Well pressure's & some of Yellowrock Well pressures

Inspection locations: Sulphur Mines Dome	**Cavern 6X**	**Cavern Well 7A**	**Cavern Well 7B**	**CL-1** (near BW-22, west side of Central Lake)	**Cavern Well 2**	**Cavern Well 2a**	**Cavern Well 4**	**Cavern Well 20**		**Yellowrock**
General Comments:R & R construction still working on containment levee		Pad dry no bubbling observed	Injecting 507 gpm down hole gauge 1471 psi	Still bubbling with an Oil sheen	Out of service due to casing leak					#1017 150 psi tubing 150 psi casing// 31012 40 psi tubing 40 psi casing// S-7 70 psi tubing 0 psi casing// S-4 20 psi tubing 180 psi casing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)			103 psi							
Casing Pressure (if applicable)	608 psi		421 psi			0.11 psi	239 psi	480 psi		
Bubbling?				yes						
Sheen?				yes						
Oil?				yes						
Odor?				yes						
Any new remedial work?				no						
Any impact to vegetation?				no						
Any impact to wildlife?				no						