INSPECTION FORM
OFFICE OF CONSERVATION
INJECTION & MINING DIVISION
617 NORTH 3RD STREET
BATON ROUGE, LA 70802

Location: Sulphur Mines Dome

Date: Monday, November 3, 2025 Time of Arrival: 9:00 AM Time of Departure: 12:00 PM

Inspector Name(s): Billy Carnes

Other personnel on site: DeAnn Chpman [Westlake] Vance Hill [Yellowrock]

Weather Conditions (Temp/Wind Speed/Direction, etc.): 57* to 70* 5 mph ENE Sunny/Clear

Any planned work for today: Check bubbling site's, Cavern Well pressure's & some of YellowrockWell pressures

Inspection locations: Sulphur Mines Dome	**Cavern 6X**	**Cavern Well 7A**	**Cavern Well 7B**	**CL-1** (near BW-22, west side of Central Lake)	**Cavern Well 2**	**Cavern Well 2a**	**Cavern Well 4**	**Cavern Well 20**		**Yellowrock**
R & R Construction working on containment levee		Pad dry no bubbling observed	injecting 509 gpm //down hole gauge reading 1470	Still bubbling with a Oil sheen	Out of service					#1017 50 psi tubing 50 psi casing// #1012 40 psi tubing 40 psi casing// S-7 70 psi tubing 0 psi casing// S-4 20 psi tubing 170 psi casing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)			101 psi							
Casing Pressure (if applicable)	607 psi		419 psi			0.23 psi	244 psi	462 psi		
Bubbling?				yes						
Sheen?				yes						
Oil?				yes						
Odor?				yes						
Any new remedial work?				no						
Any impact to vegetation?				no						
Any impact to wildlife?				no						