INSPECTION FORM
OFFICE OF CONSERVATION
INJECTION & MINING DIVISION
617 NORTH 3RD STREET
BATON ROUGE, LA 70802

Location: Sulphur Mines Dome

Date: Monday, November 10, 2025 Time of Arrival: 9:00 AM Time of Departure: 12:00 PM

Inspector Name(s): Billy Carnes

Other personnel on site: Vance Hill [Yellowrock] DeAnn Chapman [Westlake]

Weather Conditions (Temp/Wind Speed/Direction, etc.): 47* to 55* 9 mpn N clear & cool

Any planned work for today: Check bubbling site's, Cavern Well pressures & some of Yellowrock Well pressures

Inspection locations: Sulphur Mines Salt Dome	**Cavern 6X**	**Cavern Well 7A**	**Cavern Well 7B**	**CL-1** (near BW-22, west side of Central Lake)	**Cavern Well 2**	**Cavern Well 2a**	**Cavern Well 4**	**Cavern Well 20**		**Yellowrock**
R & R Construction working on the containment levee		Pad dry no bubbling observed	injecting 514 psi gpm// downhole gauge reading 1469 psi	Still bubbling with Oil sheen	Well is out of service					#1017 30 psi tubing 30 psi casing// #1012 40 psi tubing 40 psi casing// S-7 70 psi tubing 0 psi casing// S-4 20 psi tubing 170 psi casing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)			102 psi							
Casing Pressure (if applicable)	606 psi		418 psi			0.19 psi	249 psi	490 psi		
Bubbling?				yes						
Sheen?				yes						
Oil?				yes						
Odor?				yes						
Any new remedial work?				no						
Any impact to vegetation?				no						
Any impact to wildlife?				no						