# INSPECTION FORM
# OFFICE OF CONSERVATION
# INJECTION & MINING DIVISION
# 617 NORTH 3RD STREET
# BATON ROUGE, LA 70802

Location: Sulphur Mines Dome

Date: Monday, November 17, 2025 Time of Arrival: 9:30 AM Time of Departure: 12:00 PM

Inspector Name(s): Billy Carnes

Other personnel on site: Vance Hill [Yellowrock] DeAnn Chapman [Westlake] Clay Trahan [Stan's Airboats]

Weather Conditions (Temp/Wind Speed/Direction, etc.): 73* to 79 * 7 mph SSE partly cloudy

Any planned work for today: Check Bubbling site's with the Airboat in central pond/lake also check Cavern Well pressure's & some of Yellowrock Well pressures

| **Inspection locations:** Sulphur Mines Salt Dome | **Cavern 6X** | **Cavern Well 7A** | **Cavern Well 7B** | **CL-1** (near BW-22, west side of Central Lake) | **Carern Well 2** | **Cavern Well 2a** | **Cavern Well 4** | **Cavern Well 20** | **CL Bubbling Site's** | **Yellowrock** |
|---|---|---|---|---|---|---|---|---|---|---|
| R & R Construction working on containment levee. ERM later today will be getting air & water samples | | Pad dry NO bubbling observed | Injecting 519 gpm // downhole gauge 1471 psi | Still bubbling with oil sheen | out of service | | | | CL- 3,4,5,6,23 & 24 were bubbling & time of inspection all others were inactive | #1017 160 psi tubing 160 psi casing// #1012 40 psi tubing 40 psi casing// S-7 70 psi tubing 0 psi casing//S-4 20 psi tubing 170 psi casing |
| Photos taken? (save to F: drive) | | | | | | | | | | |
| Tubing Pressure (if applicable) | | | 103 psi | | | | | | | |
| Casing Pressure (if applicable) | 607 psi | | 419 psi | | | 0.31 psi | 254 psi | 450 psi | | |
| Bubbling? | | | | yes | | | | | | |
| Sheen? | | | | yes | | | | | | |
| Oil? | | | | yes | | | | | | |
| Odor? | | | | yes | | | | | | |
| Any new remedial work? | | | | no | | | | | | |
| Any impact to vegetation? | | | | no | | | | | | |
| Any impact to wildlife? | | | | no | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |