INSPECTION FORM
OFFICE OF CONSERVATION
INJECTION & MINING DIVISION
617 NORTH 3RD STREET
BATON ROUGE, LA 70802

Location: Sulphur Mines Dome

Date: Monday, November 24, 2025 Time of Arrival: 10:00 AM Time of Departure: 12:00 PM

Inspector Name(s): Billy Carnes

Other personnel on site: Randy Brousard [Westlake] Vance Hill [Yellowrock]

Weather Conditions (Temp/Wind Speed/Direction, etc.): 71* to 78* Cloudy w/light rain 11 mph SSE

Any planned work for today: Check bubbling sites, Cavern Well pressures & some of Yellowrock Well pressures

Inspection locations: Sulphur Mines Salt Dome	**Cavern 6X**	**Cavern Well 7A**	**Cavern Well 7B**	**CL-1** (near BW-22, west side of Central Lake)	**Cavern Well 2**	**Cavern Well 2a**	**Cavern well 4**	**Cavern Well 20**		**Yellowrock**
R & R Construction is still working in the containment levee.		Pad had fluid on it bubbling observed	Injecting @ 500 gpm & bottom hole pressure gauge reading was 1471 psi	Still bubbling w/oil sheen	this cavern is out of service					#1017 100 psi tubing 100 psi casing// #1012 40 psi tubing 40 psi casing// S-7 70 psi tubing o psi casing// S-4 20 psi tubing 170 psi casing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)			104 psi							
Casing Pressure (if applicable)	607 psi		421 psi			0.39 psi	259 psi	450 psi		
Bubbling?		yes		yes						
Sheen?		no		yes						
Oil?		no		yes						
Odor?		no		yes						
Any new remedial work?		no		no						
Any impact to vegetation?		no		no						
Any impact to wildlife?		no		no						