INSPECTION FORM
OFFICE OF CONSERVATION
INJECTION & MINING DIVISION
617 NORTH 3RD STREET
BATON ROUGE, LA 70802

Location: Sulphur Mines Dome

Date: Monday, December 1, 2025 Time of Arrival: 9:30 AM Time of Departure: 12:30 PM

Inspector Name(s): Billy Carnes

Other personnel on site: Kevin LaVergne [Westlake] Vance Hill [Yellowrock]

Weather Conditions (Temp/Wind Speed/Direction, etc.): 47* to 48* 5 mph NE cloudy rainy

Any planned work for today: Check out bubbling sites, Cavern Well pressures & some of Yellowrock Well pressures

Inspection locations: Sulphur Mines Salt Dome	**Cavern 6X**	**Cavern Well 7A**	**Cavern Well 7B**	**CL-1** (near BW-22, west side of Central Lake)	**Cavern Well 2**	**Cavern Well 2a**	**Cavern Well 4**	**Cavern Well 20**		**Yellowrock**
R & R Construction still working on containment levee		Fluid on pad bubbling observed	Injecting 530 gpm down hole gauge reading 1470 psi	bubbling w/oil sheen	is out of service					#1017 90 psi tubing 90 psi casing// #1012 40 psi tubing 40 psi casing// S-7 70 psi tubing 0 psi casing// S-4 20 psi tubing 155 psi casing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)			101 psi							
Casing Pressure (if applicable)	606 psi		418 psi			0.50 psi	263 psi	458 psi		
Bubbling?		yes		yes						
Sheen?		no		yes						
Oil?		no		yes						
Odor?		no		yes						
Any new remedial work?		no		no						
Any impact to vegetation?		no		no						
Any impact to wildlife?		no		no						