INSPECTION FORM
OFFICE OF CONSERVATION
INJECTION & MINING DIVISION
617 NORTH 3RD STREET
BATON ROUGE, LA 70802

Location: Sulphur Mines Dome

Date: Monday, December 8, 2025 Time of Arrival: 9:30 AM Time of Departure: 1:00 PM

Inspector Name(s): Billy Carnes

Other personnel on site: DeAnn Chapman [Westlake] Vance Hill [Yellowrock]

Weather Conditions (Temp/Wind Speed/Direction, etc.): 51* to 56* clear skies 10 mph NNE

Any planned work for today:

Inspection locations: Sulphur Mines Salt Dome	**Cavern 6X**	**Cavern Well 7A**	**Cavern Well 7B**	**CL-1** (near BW-22, west side of Central Lake)	**Cavern Well 2**	**Cavern Well 2a**	**Cavern Well 4**	**Cavern well 20**		**Yellowrock**
		Injecting 536 gpm downhole gauge 1470 psi	Fluid on pad bubbling observed	still bubbling w/oil sheen	This Cavern is out of service					#1017 90 psi tubing 90 psi casing// #1012 40 psi tubing 40 psi casing// S-7 70 psi tubing 0 psi casing// S-4 20 psi tubing 400 psi casing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)		102 psi								
Casing Pressure (if applicable)	605 psi	419 psi				0.39 psi	268 psi	486 psi		
Bubbling?			yes	yes						
Sheen?			no	yes						
Oil?			no	yes						
Odor?			no	yes						
Any new remedial work?			no	no						
Any impact to vegetation?			no	no						
Any impact to wildlife?			no	no						