INSPECTION FORM
OFFICE OF CONSERVATION
INJECTION & MINING DIVISION
617 NORTH 3RD STREET
BATON ROUGE, LA 70802

Location: Sulphur Mines Dome

Date: Monday, December 15, 2025 Time of Arrival: 9:30 AM Time of Departure: 12:00 PM

Inspector Name(s): Billy Carnes

Other personnel on site: DeAnn Chapman [Westlake] Vance Hill [Yellowrock]

Weather Conditions (Temp/Wind Speed/Direction, etc.): 39* to 44* clear skies/cool NE 6 mph

Any planned work for today: Check bubbling sites, Cavern Well pressures & some of Yellowrock Well pressures

Inspection locations: Sulphur Mines Salt Dome	**Cavern 6X**	**Cavern Well 7A**	**Cavern Well 7B**	**CL-1** (near BW-22, west side of Central Lake)	**Cavern Well 2**	**Cavern Well 2a**	**Cavern Well 4**	**Cavern Well 20**		**Yellowrock**
R & R Construction working on containment levee		Fluid on pad bubbling observed	Injecting 557 gpm down hole gauge 1472 psi	Still bubbling w/oil sheen	Well is out of service					#1017 40 psi tubing 40 psi casing// #1012 40 psi tubing 40 psi casing// S-7 70 psi tubing 0 psi casing// S-4 22 psi tubing 380 psi casing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)			103 psi							
Casing Pressure (if applicable)	604 psi		418 psi			0.35 psi	272 psi	509 psi		
Bubbling?		yes		yes						
Sheen?		no		yes						
Oil?		no		yes						
Odor?		no		yes						
Any new remedial work?		no		no						
Any impact to vegetation?		no		no						
Any impact to wildlife?		no		no						