INSPECTION FORM
OFFICE OF CONSERVATION
INJECTION & MINING DIVISION
617 NORTH 3RD STREET
BATON ROUGE, LA 70802

Location: Sulphur Mines Dome

Date: Monday, December 22, 2025 Time of Arrival: 11:00 AM Time of Departure: 12:30 PM

Inspector Name(s): Sarah Hitchcock

Other personnel on site: Randy Broussard (Westlake), Vance Hill (Yellow Rock)

Weather Conditions (Temp/Wind Speed/Direction, etc.): 69 degrees, Wind East at 5 mph

Any planned work for today: Check bubbling site, cavern well pressures, and some of Yellow Rock well pressures

Inspection locations: Sulphur Mines Salt Dome	**Cavern 6X**	**Cavern Well 7A**	**Cavern Well 7B**	**CL-1** (near BW-22, west side of Central Lake)	**Cavern Well 2**	**Cavern Well 2a**	**Cavern Well 4**	**Cavern Well 20**		**Yellowrock**
		Water present and bubbling observed on well pad	Injecting 555 gpm/ downhole gauge 1471 psi	Bubbling with oil present	Well is out of service					Well No. 1017 30 psi tbg, 30 psi csg//Well No. 1012 40 psi tbg, 40 psi csg//Well No. S-7 70 psi tbg, 0 psi csg// Well No. S-4 20 psi tbg, 390 psi csg
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)			103							
Casing Pressure (if applicable)			420			0.70 psi	277 psi	470 psi		
Bubbling?		yes		yes						
Sheen?		no		yes						
Oil?		no		yes						
Odor?		no		yes						
Any new remedial work?		no		no						
Any impact to vegetation?		no		no						
Any impact to wildlife?		no		no						