INSPECTION FORM
OFFICE OF CONSERVATION
INJECTION & MINING DIVISION
617 NORTH 3RD STREET
BATON ROUGE, LA 70802

Location: Sulphur Mines Dome

Date: Monday, January 5, 2026 9:30 AM 1:00 PM

Inspector Name(s): William Carnes

Other personnel on site: Kever LaVergne [Westlake] Vance Hill [Yellowrock

Weather Conditions (Temp/Wind Speed/Direction, etc.): 52* to 67* partly cloudy 6 mph S

Any planned work for today: Check bubbling sites, cavern well pressures, and some of Yellow Rock well pressures

Inspection locations: Sulphur Mines Salt Dome	**Cavern 6X**	**Cavern Well 7A**	**Cavern Well 7B**	**CL-1** (near BW-22, west side of Central Lake)	**Cavern Well 2**	**Cavern Well 2a**	**Cavern Well 4**	**Cavern Well 20**		**Yellowrock**
R & R Construction working on containment levee		Pad dry no bubbling observed	Injecting 556 gpm Downhole gauge 1469 psi	Still bubbling with oil sheen	Well is out of service					#1017 100 psi tubing 100 psi casing// #1012 40 psi tubing 40 psi casing//S-7 70 psi tubing 0 psi casing// S-4 22 psi tubing 370 psi casing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)			102 psi							
Casing Pressure (if applicable)	604 psi		417 psi			0.15 psi	284 psi	522 psi		
Bubbling?				yes						
Sheen?				yes						
Oil?				yes						
Odor?				yes						
Any new remedial work?				no						
Any impact to vegetation?				no						
Any impact to wildlife?				no						