INSPECTION FORM
OFFICE OF CONSERVATION
INJECTION & MINING DIVISION
617 NORTH 3RD STREET
BATON ROUGE, LA 70802

Location: Sulphur Mines Dome

Date: Monday, January 20, 2025 Time of Arrival: 8:25 AM Time of Departure: 11:30 AM

Inspector Name(s): William Carnes

Other personnel on site: DeAnn Chapman [Westlake] Vance Hill [Yellowrock] Brad Buller [Stan's Airboats]

Weather Conditions (Temp/Wind Speed/Direction, etc.): 47* to 63* partly cloudy 5 mph ESE

Any planned work for today: Check bubbling sites, cavern well pressures, and some of Yellow Rock well pressures

Inspection locations: Sulphur Mines Salt Dome	**Cavern 6X**	**Cavern Well 7A**	**Cavern Well 7B**	**CL-1** (near BW-22, west side of Central Lake)	**Cavern Well 2**	**Cavern Well 2a**	**Cavern Well 4**	**Cavern Well 20**	**Central lake** Bubbling sites	**Yellowrock**
R & R Construction working on containment levee. ERM working on Air & Water samples. Yellowrock well #1010 tubing pressure 10 psi will add this well to inspection for a while for tubing pressure increases. Witness Sapling of MW 2 500 for Oil, had somekind of residue on probe. Observed ERM taking probe and securing it in a plastic bag.		Pad dry no bubbling observed	Injecting 561 gpm // Downhole gauge reading 1469	Still bubbling with Oil sheen	Well is out of service				Observed bubbling sites 3,4,5,6,23 & 24 active today, all others were inactive @ time of inspection	psi tubing 10 psi casing// #1017 90 psi tubing 90 psi casing// #1012 40 psi tubing 40 psi casing// S-7 70 psi tubing 0 psi casing// S-4 22 psi tubing 350 psi casing
Photos taken? (save to F: drive)										
Tubing Pressure (if applicable)			102 psi							
Casing Pressure (if applicable)	604 psi		418 psi			0.62 psi	284 psi	531 psi		
Bubbling?		yes		yes						
Sheen?		no		yes						
Oil?		no		yes						
Odor?		no		yes						
Any new remedial work?		no		no						
Any impact to vegetation?		no		no						
Any impact to wildlife?		no		no						